



EXAMPLE: Typical Arrangement of Extrusion Tooling in the Press


Hollow (Porthole) Die Tooling Arrangement



Flat (Solid) Die with Feeder Tooling Arrangement



Flat (Solid) Die with Cavity Tooling Arrangement



Flat (Solid) Die, no cavity or feeder, Tooling Arrangement

